

FIG. 1




FIG. 2




FIG. 3





FIG. 4



IMPROVEMENT IN THICKNESS UNIFORMITY  
CAUSED BY INCREASE IN FLOW RATE of  $O_3$   
(MEASURED AT ANY 13 POINTS)

FIG. 5

